

Oil Field Environmental Incident Summary

Incident: 20150620104542 **Date/Time of Notice:** 06/20/2015 10:45

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: VOODOO 1-22

Field Name: ROOSEVELT

Well File #: 13108

Date Incident: 6/19/2015 **Time Incident:** 17:00

Facility ID Number:

County: BILLINGS

Twp: 142

Rng: 102

Sec: 22

Qtr: NW NE

Location Description:

Submitted By: Kaylan Dirkx

Received By:

Contact Person: Kaylan Dirkx
P.O Box 1589
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	20	Barrels	19	Barrels	19	barrels
Brine	10	Barrels	9	Barrels	9	barrels

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 10/19/2015 **Clean Up Concluded:** 7/20/2015

Risk Evaluation:

None- spill was contained.

Areal Extent:

Potential Environmental Impacts:

None- spill was contained. Free liquids were recovered and returned to production tanks on 6/19/15. Any impacted material will be removed and disposed at an approved facility

Action Taken or Planned:

Firetube will be replaced and inspected to determine cause. 6/19: Free liquids were recovered and returned to production tanks. 6/22: Any impacted material will be removed and disposed at an approved facility

Wastes Disposal Location: Liquids - returned to production tanks. Impacted soil -approved facility

Agencies Involved:**Updates**

Date: 6/22/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to treater leak, remained on location within the diking, according to the report. NDIC retains oversight.